

Recommendation for a shielded cage / EEG lab

Materials:


Side walls, doors & floor:
Ferromagnetic steel profile/sheet

Windows & roof:
Perforated steel sheet

NO POWER SUPPLY
INSIDE THE CAGE !

NO POWER LINE INSIDE
THE CAGE !

NO ELECTRIC LIGHT
INSIDE THE CAGE !



All parts of the cabin should have an electrically
conductive connection to each other (doors, windows, chair, ...).
Cable feedthrough as small as possible !